

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182604
Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Robb Popp	Partial	Thursday, June 18, 2020

Corrective Action Required:

1	Miscellaneous Correction	-4TH FLOOR CENTER- -INSTALL SIGNAGE THROUGHOUT
---	--------------------------	---

Corrective Action Required:

2	Miscellaneous Correction	-3RD FLOOR CENTER- -INSTALL SIGNAGE THROUGHOUT -INSTALL SIDING/TRIM AT PATIO GFCI
---	--------------------------	---

Corrective Action Required:

3	Miscellaneous Correction	-2ND FLOOR CENTER- -INSTALL SIGNAGE THROUGHOUT -MOTHER IN LAW- WATER HEATER DISCHARGE IN PAN DRAIN, NO OUTLET FOR DISHWASHER AND DISPOSAL, MISSING ARCH FALULT BREAKER
---	--------------------------	--

Corrective Action Required:

4	Miscellaneous Correction	-1ST FLOOR- CLUBHOUSE -INSTALL SIGNAGE THROUGHOUT -EPO FOR SPA
---	--------------------------	---

Corrective Action Required:

5	Miscellaneous Correction	<p>-4TH FLOOR LEFT WING-</p> <p>-INSTALL SIGNAGE THROUGHOUT</p> <p>-425-SOFT OUTLET GFCI AT PAIO</p> <p>-426-TIGHTEN MIDDLE POST ON PATIO RAILING SOUTH SIDE</p> <p>-427-HAMMER ARRESTORS AT KITCHEN SINK, INSTALL SHOWER HEAD, FAULTY GFCI BY FRIDGE, MISSING COVER PLATE IN OFFICE</p> <p>-430 TIGHTEN MIDDLE POST ON PATIO RAILING, 3 KITCHEN OUTLETS NEED GFCI PROTECTION</p>
---	-----------------------------	---

Comments: