## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20193622Address:1824 SW RIVER RUN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Wednesday, June 24, 2020
Informational:			
1 Misc	- Inspected garage portal -		
Corrective Action Required:			
2 Miscellaneous	scellaneous Tighten anchor bolts in garage		
Correction	Protect NM in garage by laundry room		
	Fire stop joint of double wall top plate in laundry		
	Nail corners and wall intersections per code		
	Missing Smoke and co2 detector outside of bedrooms		
	Seal around flue in chase wall in hall		
	Block joists above wall at cantilevers		
	Missing hanger on joist southeast corner at cantilever		
	Fire block beam webs		
	Nail double 2x10 joists in basement family room		
	Provide treated wood where in contact with concrete in the storm shelter		
	Tighten anchor bolts in basement		
	Fire stop furred out wall at walk in and basement mechanical room		
	Pressure valve on gas gauge broken		
	Fire stop floor joist and wall top plate near subpanel		
	Fire stop Recess gap in sheathing in mechanical room with sub panel		
	Provide hanger connections where deck joist meets corner of house		

**Comments:**