CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182604

Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Miscellaneous Inspection Robb Popp Partial Wednesday, July 15,

2020

Informational:

1 Miscellaneous Correction

RIGHT WING*

-4TH FLOOR-

SIGNAGE THROUGHOUT

CLARIFY LACK OF OVERFLOW PROTECTION FOR HOT WATER HEATERS-ALL

UNITS

401-TIGHTEN CENTER POST AT PATIO RAILING, LOOSE OUTLET AT BAR

405- BAD GFCI AT EXTERIOR

407- MISSING SINK FIXTURE IN BATHROOM

MECHANICAL CLOSET- MISSING COVER PLATE AND BONDING OF METALLIC

BOX AT CEILING

ELEVATOR EQUIPMENT ROOM- COMPLETE INSTALLATION OF WIRING NO OVERFLOW PROTECTION FOR HOT WATER HEATERS-ALL UNITS

-3RD FLOOR-

SIGNAGE THROUGHOUT

CLARIFY LACK OF OVERFLOW PROTECTION FOR HOT WATER HEATERS-ALL

UNITS

302- SEAL PENETRATION IN MECHANICAL ROOM, FAULTY GFCI BY RANGE TIED

TO ISLAND RECEPTACLES
303- LOOSE GFCI AND RECEPTACLE IN BATHROOM
307- SOFT GFCI AT EXTERIOR PATIO, BAD GFCI BY RANGE TIED TO ISLAND
RECEPTACLES
309- OPEN GROUND AT GFCI BY RANGE
STAIRWELL 2- SECURE OPERABLE WINDOW FOR FALL PROTECTION

Comments: