CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200388

Address: 4725 NE SARATOGA CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, July 22,

Residential 2020

Corrective Action Required:

1 Misc FRAMING:

- -Fb foyer wall from roof
- -Install hanger support for foyer IvI beams
- -Support rafters to 2x10 purlin with hangers or blocking underneath rafters
- -Shim gap at front porch beam support inside front bedroom
- -Front bedroom gable wall studs not continuous
- -Support ridge above front bedroom
- -Anchor garage portal walls sill plates per code
- -Have engineer address non-continuous 2x4 studs in exterior wall exceeding 12 ft in garage and front bedroom
- -Support hip rafters at ridge above great room
- -Support underneath master bedroom ceiling beam point load to I beam below
- -Nail corner studs per code
- -Fb fireplace space from roof. Use 3/4" sheathing or other approved materials
- -Fb double stud wall in basement vertically every ten ft of less
- -Toe nail joists to basement sill plate and top plates with 3-10d or 4-8d box nails

ELECTRICAL:

- -Protect wiring within six ft of attic access
- -Protect wiring at rear dining area where located within 1.25" of framing

surface

**OK TO INSULATE

Comments: