

# Inspection Summary

Permit #: PRSUBD20184050, Development - Subdivision  
SUMMIT VIEW FARMS 3RD PLAT SUBDIVISION IMPROVEMENTS

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Thursday, July 23, 2020

Corrective Action Required

- 1 Your project is in violation of the Erosion and Sediment control policy. We received an email with pictures of erosion control problems on this site from the Missouri Department of Natural Resources. There appears to be a can of trash that was dumped in the road at a dead end. All the gutter buddy's in the curb inlets need to be cleaned out of the mud and silt. Some of them are growing weeds in them. Please take care of these items as soon as possible. We will check back on Tuesday July 28. Please notify the builders to make sure their erosion control devices are in place.

Comments: