

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500
NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Ronald Paynter	Partial	Friday, July 31, 2020

Corrective Action Required:

1	Misc	Silt is washing up on 113, 109, 105 and 101 NW Cody Dr. Silt fence is down in one spot. Might need to design a silt trap basin for this area. Silt was also washing down the field inlet behind 117 NW Cody Dr. RP 8-26-19
---	------	--

Corrective Action Required:

2	Misc	Silt fence protecting Ambersham off Whitman has washed out and is allowing silt to leave the work site. Fencing needs to be repaired and SWPPP needs to be re-evaluated to avoid further violations. Future violations could lead to stop work orders being issued. RP 8-28-19
---	------	--

Corrective Action Required:

3	Misc	Silt fence on Ambersham has been breeched in numerous spots, dumping silt down Ambersham and Whitlock. Need to get repair erosion control and remove silt from roadways. RP 5-28-20
---	------	---

Informational:

4	Misc	Silt has been swept up from the roadways. Welch Erosion still needs to repair erosion control devices. RP 5-29-20
---	------	---

Corrective Action Required:

5	Misc	SWWWP report from Welch Erosion had nothing listed for the erosion issues off of Ambersham last Thursday. RP 6-2-20
---	------	---

Informational:

6	Misc	No work is being done today due to last nights storm. No erosion issues and
---	------	---

Corrective Action Required:		the fence that was down on Ambersham has been repaired. RP 6-4-20
7	Misc	Still need phase 2 erosion controls implemented. Also need curb inlets cleaned out and gutter buddies replaced and installed correctly. RP 7-30-20
Corrective Action Required:		
8	Misc	Yesterday's rain deposited a lot of silt on Whitlock, Joshua and Ambersham. Welch Erosion is on site cleaning curb inlets and checking perimeter fencing. I informed them on the silt in the roadways also. RP 7-31-20

Comments: