

Inspection Summary

Permit #: PRCOM20192156, Building Permit - Commercial
MCKEEVER'S MARKET
Address: 840 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Field Services	Joe Starlin	Failed	Thursday, August 06, 2020

Informational

1. Sidewalk out front has 2 panels missing
2. We need a substantial completion for the off-site public road improvements and a partial substantial completion for the private road. These item are to be taken care of by the developer. We have no items that McKeever's has to do.

Occupancy Inspection - Codes Commercial	Michael Harkins	Temporary C of O	Thursday, August 06, 2020
---	-----------------	------------------	---------------------------

Corrective Action Required

- 1 - TCO TO TRAIN & STOCK ONLY -
:
- LABLE RTU DISCONNECTS -
- WOMENS RESTROOM STALL DOOR -
- FIRE CAULK CEILING DRY SPRINKLER ROOM -

Occupancy Inspection - Fire	Michael Weissenbach	Passed	Thursday, August 06, 2020
-----------------------------	---------------------	--------	---------------------------

Occupancy Inspection - Water Utilities	Curtis Deason	Passed	Thursday, August 06,
--	---------------	--------	----------------------

Comments:
