

August 6, 2020

IQ Construction

Re: Lot 669, Eagle Crest – 2513 SW River Trail Road

Vista Structural Engineering, LLC, was asked to address the following two items brough forth by the city inspector during rough-in inspection:

- Address rafters landing on 2x blocks. Provide nailing of blocking to top plate and nail rafters to adjacent ceiling joists per the attached detail
- Address rafters landing on (4) 2x4 top plates. The (4) 2x4 plates shall be screwed together and the bottom of the (4) 2x4 plates shall be screwed to each stud per the attached detail.

Our firm appreciates the opportunity to serve you. If you have any questions or if you need anything further, please feel free to contact us.

