CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Michael Harkins	Partial	Wednesday, September 02, 2020
Corrective 1	Action Required: FOURTH FLOOR	AREA"E"- UNITS-438439,44 426;444,447,448,449,450, Corridor 419 to room 439 o -CORRIDOR 419,422,426, 4 AREA "D" CORRIDOR 412,	ok	9-461-462–460-
Corrective 2	Corrective Action Required:		17, 348, 349, 350, 351, 352, ok	
Corrective 3	Action Required: SECOND FLOOR	, ,	NG 312, 241,242,243,244,245, 246, 2 3,254,256,257,258,259,260,	

-248- SEAL DEAD SPACE AT FUTURE SHAFT

Corridor 219 to room 240 ok Corridor 222 to stairs ok - CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 -SECTION "E" CORRIDOR FRAMING CEILING 229, SECTION "D" CORRIDOR CEILING FRAMING 212, Corrective Action Required: FIRST FLOOR **BUILDING "B"** -CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY BUILDING "C" AREAS OK; -LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY Section "E" OK-124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135 Corridor 119 to room 125 ok Corridor 122 to stairs ok CORRIDOR CEILING 112, 129, -Corridor 126 Metal Stud Framing from north exit to line 8.6 -CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132--SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments:

4