## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Michael Harkins	Partial	Wednesday, September 16, 2020
Correctiv 1	e Action Required: Miscellaneous Correction	RETAIL AREA "B" -AREAS APPROVED-		
Correctiv 2	-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTEP SHEATHING SCREW PATTERN rrective Action Required: FIRST FLOOR -AREAS APPROVED- AREA "E"		O 4.4 EXTERIOR	
		CEILING - UNITS-126 2ND LAYER -	A,124,125,126,127,128,129, 5,127,128,129, 132, 133,134	
Correctiv 3	e Action Required: SECOND FLOOR	2ND LAYER UNITS 124,125 \-AREAS APPROVED- AREA "E"	5,127,128,129,132,133,134,	135, -

	RC CHANNEL WALLS AND CEILINGS: CORRIDORS 219 222,226, 227, 221A,240-245,261-264 - - RC CHANNEL CORRIDOR 229 CEILING ONLY -
	1ST LAYER-222,226
	SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO ROOM 241, CORRIDOR 222 TO STAIRS
	1ST LAYER UNITS: 221A,241,242,243,244,245,262,262,263; 240,264 - - 2ND LAYER UNITS 240,241,242,243, 244, 245,262,262,263, 264, -
	- 1ST LAYER MECHANCICAL CHASES 2ND FLOOR -
Corrective Action Required:	- "E" RC CHANNEL CELINGS & WALLS 224A,225A,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260, -
4 THIRD FLOOR	AREA "E"
	-AREAS APPROVED-
	RC CHANNEL - 321A,340,364 RC CHANNEL CORRIDORS- 322,326,327,319 RC CHANNEL CORRIDOR CEILING ONLY 329, - RC CHANNEL PARTY WALLS
	324A,325A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -
	1ST LAYER CEILING- 322, 326 TO ROOM 355.
	1STLAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS
	SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS:
	341,342,343,344,345,361,362,363 - RC CHANNEL
	- RC CHANNEL 324A,346, 347,348,349,350,351,352,353,354,355,356,357,358,359,360, -
	- 1ST LAYER UNIT 321A,324A,325A,340, 346,347,349,350,351,352,353,354,355,356,357,358,359,360,364, - - 2ND LAYER UNIT 340,364,
	- 3RD FLOOR MECHANICAL CHASE 1ST LAYER COMPLETE - - CORRIDOR 322 1ST LAYER WALL - - CORRIDOR 326 1ST LAYER WEST WALL -
Corrective Action Required: 5 FOURTH FLOOR	-AREAS APPROVED- AREA "E"

		-RC CHANNEL WALLS AND CEILING 438-453, 459-462 -RC CORRIDOR 421A,422, 426, 427, - RC CORRIDOR 429 CEILING ONLY - - RC CHANNEL PARTY WALLS 424,425A,444,445,446,447,448,449,450,451,452,453,454,455,456,457,456,		
		SCREW PATTERN 1ST, 2ND LAYER WALLS CORRIDOR 419 TO ROOM 439 SCREW PATTEN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS: 439,440,441,442,443,459,460,461		
		- AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST LAYER		
		RC CHANNEL 414A, 444,445,446,447,448,449,450,451 ,452,453,454,455,456,457, -		
		- 1ST LAYER UNITS 438, 462, 421A,424A, 425A -		
		- 2ND LAYER UNITS 438, 462,421A,425A -		
		- BLDG "E" PHASE 2 1ST LAYER		
		444,445,446,447,448,449,450,451,452,453,454,455,		
		456,457,458 -		
		2ND LAYER: 444,445,447,448,449,450,451,452,453,454,455,456,		
		457,458 -		
		- CORRIDOR 429 1ST LAYER LID -		
		- CORRIDOR 422 1ST LAYER -		
		- CORRIDOR 426 1ST LAYER WEST WALL -		
Corrective Action Required:				
6	STAIR TOWER 1	STAIR TOWER "A"		
		AREAS OK:		
		-1ST LAYER SHEATHING TO 3RD FLOOR;		
		-2ND LAYER SHEATHING TO 3RD FLOOR		
Corrective Action Required:				
7	ELEVATOR 2	ELEVATOR "B"		
		AREAS OK: -SHEATHING ON NORTH AND SOUTH WALLS (TYPE A) -FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS - - 2ND LAYER "B" ELEVATOR WALLS - 1ST LAYER "B" 3RD & 4TH FLOOR SHAFT WALL- - 2ND LAYER "B" 3RD & 4TH FLOOR SHAFT WALL -		

## Comments: