CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20200162

Address: 1709 SW 27TH ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - John Morris Not Ready Monday, September

Residential 21, 2020

Corrective Action Required:

1 Miscellaneous -PROVIDE ADEQUATE EROSION CONTROL

Correction AND CLEAN UP TRASH AND DEBRIS FROM STREETS BEFORE FURTHER

INSPECTION

- MINIMUM OF (2) 2X4 BEARING STUDS

REQUIRED PER PLANS

-PROVIDE HANGERS OR 1 1/2" BEARING FOR RAFTERS OVER ENTRY

-PROVIDE HANGERS FOR JOISTS OVER ENTRY

-SEAL DEAD SPACE AT DOUBLE WALL AT STAIRS TO PREVENT VERTICAL TO HORIZONTAL FIRE SPREAD- USE APPROVED MATERIALS PER R302.11.1 -PROVIDE HANGER OR 1 1/2" BEARING FOR STRUT SUPPORTING RIDGE

LANDING ON FACE OF LVL IN GREAT ROOM

-PROVIDE VERTICAL FIRESTOP IN BASEMENT BATH OFF OF STORAGE ROOM

FUR OUT WALL WHERE GREATER THAN 10' HORIZONTAL

-FIRESTOP DEAD SPACE IN BASEMENT FIREPLACE- USE APPROVED MATERIALS PER R302.11. FIREBLOCKING REQUIRED BETWEEN FLOORS AND JOST SPACES

PER R1003.19-

-ADDRESS MISSING DOUBLE LVLS AT HEADERS REQUIRED PER HEADER

SCHEDULE

-ADDRESS SINGLE LVL HEADERS USED IN PLACE OF DOUBLE 2X10 HEADERS

REQUIRED PER HEADER SCHEDULE

-ADDRESS ALL HEADERS TO BEAR ON MINIMUM OF (2) 2X4 PER FRAMING

NOTES

Corrective Action Required:

2 Misc 9/21/20- Inspection denied due to lack of compliance with site inspection on

9/16/20

Comments: