## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Partial	Friday, November 06, 2020
Corrective Action Required: 1 FOURTH FLOOR			A 5 -
			7,428,
	-AREA "B"- - CORRIDOR 409 JOIST HA - CORRIDOR 405 JOIST HA - CORRIDOR 403 JOIST HA	NGERS -	

		: CORRECTIONS BELOW : :- CORRIDOR 411 ADD BLOCKING & NAIL J HANGER -:
Corrective	Action Required:	CONTROL TI ADD DEOCKING & NALEJ HANGEN .
2	THIRD FLOOR	Section "E"
		345-344-343- 342-361-362-363-341-364-340-322-326-327, 329, -corridor
		framing ceiling
		-320A,321A, 324A, 325A, 337, 338, 339, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360,365, 366, 367, -
	Corridor 319 to room 364 ok	
	Corridor 322, 326, 327, 329,	
		SECTION "D"
		CORRIDOR FRAMING CEILING 312, - AREA "B"
		- CORRIDOR 311, JOIST HANGERS -
		- CORRIDOR 309, JOIST HANGERS -
		- CORRIODR 305, JOIST HANGERS -
Corrective Action Required: 3 SECOND FLOOR		- CORRIDOR 301, JOIST HANGERS -
		-303,304,305,306,307,323,324,325,326,327,328,329,
		330,331,332,333,334,335,336,-
	Action Required: SECOND FLOOR	'Section "E" Ok- 220A,224A,237,238,239,240,241,242,243,244,245, 246,
		261,262. 225A, 226, 264,265,266,267 -
	-,247,249,250,251,252, 253,254,256,257,258,259,260,	
		-248- SEAL DEAD SPACE AT FUTURE SHAFT
		Corridor 219 to room 240 ok
		Corridor 222 to stairs ok
		- CORRIDOR 222 FROM STAIRS TO END OF CORRIDOR 226 - SECTION "E"
		- CORRIDOR 229 ALL ROUGH -
		SECTION "D"
		CORRIDOR CEILING FRAMING 212, -SECTION "B" -
		-CORRIDOR 209 JOIST HANGERS -
		- CORRIDOR 205, JOIST HANGERS -
		- CORRIDOR 203, JOIST HANGERS -
		- CORRIDOR 201 JOIST HANGERS -
		- CORRIDOR 211 JOIST HANGERS - - 203,204,205,206,207,223,224,225,226,227,228,229,
		230,231,232,233,234,235,236 -
	Action Required:	
4	FIRST FLOOR	BUILDING "B"
		-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL \*\*METAL FRAMING ONLY -

- 2ND TIER LOBBY NORTH & SOUTH WALLS AT RESTROOMS -
- NORTH RETAIL ALL ROUGH ----
- RETAIL E WEST WALL -
- LOWER LOBBY NORTH & SOUTH ENDS 2HR DEMISING WALL -

- UPPER & LOWER LOBBY ALL ROUGH -

Section "E" OK-120A,121,122,123,124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138,

Corridor 119 to room 125 ok Corridor 122,129 ok CORRIDOR CEILING 112, 129, -Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

- -SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT
- SECTION "B" -
- CORRIDOR 109, JOIST HANGERS -
- CORRIDOR 105, JOIST HANGERS -
- CORRIDOR 111, CEILING JOIST HANGERS :

- 101,102,103,106,107,108,109,111,112,113,117,118, 119,120, -

- 134,135 YOGA, FITNESS ROOM ABOVE CEILING ROUGH ONLY -

- 104,105,110,114,115,116 NOT READY Michael Harkins 11/06/2020 1:20 PM

Informational:

5	<b>STAIR TOWER 3</b>	STAIR TOWER 123 "C" NORTH AREAS INSPECTED:
		- STAIR TOWER "C" -
		- ALL ROUGH APPROVED -
Correcti	ve Action Required:	

6 STAIR TOWER 2 STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED: - ROUGH - IN APPROVED FLOORS 1 THRU 4 -

Comments: