CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20170411

Address: 3580 SW HOLLYWOOD DR, Unit:8, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Miscellaneous Inspection Michael Harkins Failed Friday, November 06,

2020

Corrective Action Required:

1 Misc 3580 Hollywood pre final inspection

311 seal ceiling mech closet,

Deck rail 4"?

310 sprinkler heads master bedroom & closet,

Seal ceiling mech closet,

309 seal ceiling mech room, a 4" sphere shall not pass through deck railing,

308 seal ceiling mech closet,

4" deck railing?

307 seal ceiling mech closet, 306 seal ceiling mech closet, 209 seal ceiling mech closet,

207 " " 206 " " 208 " "

Above is Mike's partial list ran out of time

Below is John's partial list

PROPER AFCI PROTECTION FOR ALL UNITS CEILING/WALL JOINT IN MECH CLOSETS SEAL ALL EXTERIOR PENETRATIONS

North stair shaft/East entry door-Fireblock Sheetrock penetrations at

sprinkler equipment

North Mechanical room- fireblock penetrations, repair Sheetrock at return air, Provide electrical panel schedule and blanks for open breaker spaces S20-Fireblock ceiling penetration

S8-locked

S6-locked

IT Room-Fireblock ceiling penetrations

???1st floor corridor ceiling penetrations

104-fireblock ceiling penetrations in mechanical closet, weatherstrip exterior door, ADA unit?

102-Weatherstrip exterior door, Fireblock mechanical closet ceiling penetrations

100- Fireblock mechanical closet ceiling penetrations, Weatherstrip exterior door

201-Repair sheet rock and fire block ceiling penetrations in mechanical closet, Weatherstripping exterior door

200-Repair sheet rock and fire block ceiling penetrations in mechanical closet, Anti-tip device at stove, Weatherstrip exterior door

202-Weatherstrip exterior door, Fireblock ceiling penetrations in mechanical closet

203-Dwelling/Corredor door does not self latch, Repair sheet rock fire block ceiling penetrations mechanical closet

205- Repair sheet rock and fire block ceiling penetrations in mechanical closet

204-Fireblock penetrations in mechanical closet ceiling

305-Fireblock penetrations in mechanical closet ceiling

303-Fireblock penetrations in mechanical closet ceiling, missing sprinkler head in mechanical closet

302-Repair sheet rock in mechanical closet and fire block penetrations and ceiling, Missing sprinkler head in mechanical closet 301/302 still to do

?

PROPER AFCI PROTECTION FOR ALL UNITS

CEILING/WALL JOINT IN MECH CLOSETS

SEAL ALL EXTERIOR PENETRATIONS

North stair shaft/East entry door-Fireblock Sheetrock penetrations at sprinkler equipment

North Mechanical room- fireblock penetrations, repair Sheetrock at return air, Provide electrical panel schedule and blanks for open breaker spaces S20-Fireblock ceiling penetration

S8-locked

S6-locked

IT Room-Fireblock ceiling penetrations

???1st floor corridor ceiling penetrations

104-fireblock ceiling penetrations in mechanical closet, weatherstrip exterior door, ADA unit?

102-Weatherstrip exterior door, Fireblock mechanical closet ceiling penetrations

100- Fireblock mechanical closet ceiling penetrations, Weatherstrip exterior door

201-Repair sheet rock and fire block ceiling penetrations in mechanical

closet, Weatherstripping exterior door

200-Repair sheet rock and fire block ceiling penetrations in mechanical closet, Anti-tip device at stove, Weatherstrip exterior door

202-Weatherstrip exterior door, Fireblock ceiling penetrations in mechanical closet

203-Dwelling/Corredor door does not self latch, Repair sheet rock fire block ceiling penetrations mechanical closet

205- Repair sheet rock and fire block ceiling penetrations in mechanical closet

204-Fireblock penetrations in mechanical closet ceiling

305-Fireblock penetrations in mechanical closet ceiling

303-Fireblock penetrations in mechanical closet ceiling, missing sprinkler head in mechanical closet

302-Repair sheet rock in mechanical closet and fire block penetrations and ceiling, Missing sprinkler head in mechanical closet 301/302 still to do

Comments: