CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20170411Address:3580 SW HOLLYWOOD DR, Unit:8, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Miscellaneous Inspection	Michael Harkins	Failed	Friday, November 06, 2020	
Corrective Action Required:				
1 Misc	3580 Hollywood pre final inspection			
	311 seal ceiling mech closet,			
	Deck rail 4" ?			
	310 sprinkler heads master bedroom & closet,			
	Seal ceiling mech closet,			
	309 seal ceiling mech room, a 4" sphere shall not pass through deck railing,			
	308 seal ceiling mech closet,			
	4" deck railing ?			
	307 seal ceiling mech closet,			
	306 seal ceiling mech closet,			
	209 seal ceiling mech closet,			
	207 "	н		
	206 "	н		
	208 "	н		
	Above is Mike's partial list ran out of time			
	Below is John's partial list			
	PROPER AFCI PROTECTION FOR ALL UNITS			
	CEILING/WALL JOINT IN MECH CLOSETS			
	SEAL ALL EXTERIOR PENETRATIONS			
	North stair shaft/East entry door-Fireblock Sheetrock penetrations at			
	sprinkler equipment			

North Mechanical room-fireblock penetrations, repair Sheetrock at return air, Provide electrical panel schedule and blanks for open breaker spaces S20-Fireblock ceiling penetration S8-locked S6-locked IT Room-Fireblock ceiling penetrations ???1st floor corridor ceiling penetrations 104-fireblock ceiling penetrations in mechanical closet, weatherstrip exterior door, ADA unit? 102-Weatherstrip exterior door, Fireblock mechanical closet ceiling penetrations 100- Fireblock mechanical closet ceiling penetrations, Weatherstrip exterior door 201-Repair sheet rock and fire block ceiling penetrations in mechanical closet, Weatherstripping exterior door 200-Repair sheet rock and fire block ceiling penetrations in mechanical closet, Anti-tip device at stove, Weatherstrip exterior door 202-Weatherstrip exterior door, Fireblock ceiling penetrations in mechanical closet 203-Dwelling/Corredor door does not self latch, Repair sheet rock fire block ceiling penetrations mechanical closet 205- Repair sheet rock and fire block ceiling penetrations in mechanical closet 204-Fireblock penetrations in mechanical closet ceiling 305-Fireblock penetrations in mechanical closet ceiling 303-Fireblock penetrations in mechanical closet ceiling, missing sprinkler head in mechanical closet 302-Repair sheet rock in mechanical closet and fire block penetrations and ceiling, Missing sprinkler head in mechanical closet 301/302 still to do ? PROPER AFCI PROTECTION FOR ALL UNITS CEILING/WALL JOINT IN MECH CLOSETS SEAL ALL EXTERIOR PENETRATIONS North stair shaft/East entry door-Fireblock Sheetrock penetrations at sprinkler equipment North Mechanical room-fireblock penetrations, repair Sheetrock at return air, Provide electrical panel schedule and blanks for open breaker spaces S20-Fireblock ceiling penetration S8-locked S6-locked IT Room-Fireblock ceiling penetrations ???1st floor corridor ceiling penetrations 104-fireblock ceiling penetrations in mechanical closet, weatherstrip exterior door, ADA unit? 102-Weatherstrip exterior door, Fireblock mechanical closet ceiling penetrations 100- Fireblock mechanical closet ceiling penetrations, Weatherstrip exterior door 201-Repair sheet rock and fire block ceiling penetrations in mechanical

closet, Weatherstripping exterior door
200-Repair sheet rock and fire block ceiling penetrations in mechanical
closet, Anti-tip device at stove, Weatherstrip exterior door
202-Weatherstrip exterior door, Fireblock ceiling penetrations in mechanical closet
203-Dwelling/Corredor door does not self latch, Repair sheet rock fire block ceiling penetrations mechanical closet
205- Repair sheet rock and fire block ceiling penetrations in mechanical closet
204-Fireblock penetrations in mechanical closet ceiling
305-Fireblock penetrations in mechanical closet ceiling
303-Fireblock penetrations in mechanical closet ceiling, missing sprinkler head in mechanical closet
302-Repair sheet rock in mechanical closet and fire block penetrations and ceiling, Missing sprinkler head in mechanical closet 301/302 still to do

Comments: