# GENERAL OBSERVATION REPORT

02191565.0061 **Report Number: Service Date:** 08/31/20 **Report Date:** 09/10/20

13 - Structural Steel Observation Task:

15620 W 113th St Lenexa, KS 66219-5102

913-492-7777

Client **Project** 

DCI - Lee's Summit Axiom Northwest Construction, Inc. Attn: Norm Hellings 2001 Shamrock Rd 2232 Broadway Lee's Summit, MO Suite 101

Everett, WA 98201 Project Number: 02191565

#### **Description of locations observed:**

Interior and canopy column baseplates.

## **Description of materials observed:**

Grout under baseplates

#### Comments:

The base plates appeared to have been fully grouted prior to our observations, and we cannot comment on the type of material, mixing techniques, or placement techniques used. The grout appeared to be placed in general accordance with the project specifications, and no voids were visible between the foundation and the base plate.

### **Services:**

Terracon Rep.: Carl W. Creamer

**Reported To:** Norm Hellings (Axiom Northwest Axiom Northwest Construction **Contractor:** 

**Report Distribution:** 

(1) Axiom Northwest Construction, Inc.,

norm@axiomnw.com

**Reviewed By:** 

Feras El mussein

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials. Page 1 of 1

CT0001, 6-30-11, Rev.9