## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20202107Address:4408 SW ALABASTER CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Tuesday, January 12, 2021
Corrective Action Required:			
1 Misc	<ul> <li>-Secure all DWV 2" or less at mid point</li> <li>-Seal all penetrations through air returns and plenums -kitchen ceiling joist penetrations</li> <li>-Penetrations bored in floor joists less than 2" from end of member and less than 2" from additional bores in joist - 1st floor above refrigerator and along kitchen area - replace or submit engineered solution</li> <li>-Floor joists penetration for pex less than 2" apart, 1st floor living room near windows - replace or submit engineered solution</li> <li>-Seal all top and bottom plate penetrations - above front door 2nd floor top plate</li> <li>-Insulate first, then solid block at cantilevers per plans</li> <li>-Attic access garage per plans</li> <li>-LIB bracing per plans</li> <li>-Fireblock 2nd floor HVAC chase hall</li> <li>-structural straps at all top plates bored 50% or more all exterior walls and all interior load bearing walls</li> <li>-Stud shoes at all DWV master bath exterior wall, nail all stud shoes currently installed</li> <li>-Penetrations for NM in floor joists less than 2" from end of joist -Several</li> </ul>		

-DWV cleanout covered at bottom basement stair

**Comments:**