CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20201148Address:1610 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	on:	Inspector:	Outcome:	Date:
Erosion C	Control	Patrick Schonfeldt	Failed	Wednesday, January 13, 2021
Corrective Action Required:				
2	DCM2 ESC	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.		
	DEFICIENT			
	INSTALLATION			
		MAINTAIN SILT FENCE ON LOT, SILT FENCE REQUIRED AT FRONT OF LOT,		
		MAINTAIN GUTTER BUDDIES AT STREET STORM INLETS AND REMOVE		
		COLLECTED SILT		
		SILT FENCE REQUIRED AT BACK OF LOT, SILT FENCE CURRENTLY DOWN		
		ALLOWING SILT TO FLOW	INTO STORM INLET AT SWA	LE AT BACK OF LOT

Comments: