

#### **DEVELOPMENT SERVICES**

Building Permit - Residential	Permit No: PRRES20204954
Project Title:	Date Issued: January 14, 2021
Work Desc: NEW SINGLE FAMILY	

Project Address:345 NW AMBERSHAM DR.Permit Holder:345 NW AMBERSHAM DR, LEES SUMMIT, MO 64081CLAYTON PROPERTIES GROUP, INC

120 SE 30TH ST

Legal Description:

LEES SUMMIT, MO 64082

**Parcel No**: 224848

County: JACKSON

# **Activities Included for this Project:**

zNew Single Family, Right of Way, License Tax, License Tax Credit, Deck - Covered Residential, Driveway Permit, Sidewalk Permit,

THIS PERMIT IS ISSUED IN RELIANCE UPON INFORMATION SUBMITED BY THE APPLICANT. THE BUILDING OFFICIAL MAY SUSPEND OR REVOKE WHENEVER THE PERMIT IS ISSUED IN ERROR, OR ON THE BASIS OF INCORRECT INFORMATION SUPPLIED, OR IN VIOLATION OF ANY ADOPTED CODE, CITY ORDINANCE OR REGULATIONS.

NOTICE: THE DISPOSAL OF DEMOLITION WASTE IS REGULATED BY THE DEPARTMENT OF NATURAL RESOURCES UNDER CHAPTER 260 RSMO. SUCH WASTE, IN TYPES AND QUANTITIES ESTABLISHED BY THE DEPARTMENT, SHALL BE TAKEN TO A DEMOLITION LANDFILL OR A SANITARY LANDFILL FOR DISPOSAL.

#### **CONDITIONS**

One or more divisions have conditions that have not been addressed during the review period. The outstanding conditions provided below shall be met as indicated during the construction period.

### Residential Plan Review

1 Identify emergency escape openings from bedrooms and basement(s). (IRC Section R310 as amended per Ordinance)

NOT LABELED IN BEDROOM #2.

# Plot Plan Review

The legal description, including plat or phase number and lot number, and street address must be provided on the plot plan.

345 NW AMBERSHAM DR. IS THE CORRECT ADDRESS FOR THIS LOT.

2 Property boundary distances and bearings, as shown on the recorded plat, must be provided on the plot plan.

EAST PROPERTY BEARING AND DISTANCE DOESN'T MATCHE THE PLAT.

NORTH PROPERTY DOESN'T MATCH PLAT. PLOT PLAN SHOWS R=311' AND L=101.02' WHILE PLAT SAYS R=200' AND L=89.47

# PLEASE VERIFY.

3 Sidewalks with dimensions must be provided on the plot plan.

THE PLAT DOESN'T SHOW A SIDEWALK ON THE NW AMBERSHAM DR. SIDE. PLEASE VERIFY.

4 Existing and finish elevations at all property corners must be provided on the plot plan.

MISSING PROPERTY CORNER ELEVATIONS AT THE NORTHWEST CORNERS OF THE LOT.

Signature of	
Applicant:	Date:1-14-21
Print name:	Company Name:CLAYTON PROPERTIES GROUP