



Jason Walker <superiorrealestateservices@gmail.com>

Main St. I-Joist

2 messages

Austin, Jim <jaustin@mccraylumber.com>

Fri, Jan 29, 2021 at 9:57 AM

To: Jason Walker <superiorrealestateservices@gmail.com>

No repair needed. See below

Sent from my iPhone

Begin forwarded message:

From: DonHappel@bc.com**Date:** November 23, 2020 at 10:43:21 AM EST**To:** "Austin, Jim" <jaustin@mccraylumber.com>**Cc:** "Tally, Keith" <ktally@mccraylumber.com>**Subject:** RE: What's the fix

So it looks like there is no repair needed. When he ran the situation through his BC Calc program, taking everything into account it passed with no repair needed.

I have attached the BC Calc sheet for you to be able to give to the building inspector if needed.

Don Happel**Senior EWP Designer**

Boise Cascade

[221 NW Chipman Rd](#)[Lee's Summit, MO 64063](#)

816-347-7448 Office

913-302-5241 Cell

This message has been scanned for malware by Websense. www.websense.com


6 attachments



image001.png
9K

Boise Cascade

 **image002.png**
1K

 **image003.jpg**
1K

 **image004.png**
1K

 **image005.png**
1K

 **Calc w holes.pdf**
236K

Jason Walker <superiorrealestateservices@gmail.com>
To: Michael Harkins <michael.harkins@cityofls.net>

Fri, Jan 29, 2021 at 10:13 AM

Here is email from Boise cascade rep with attachment also

[Quoted text hidden]

--

Jason F Walker

Walker Custom Homes LLC
Owner

913-208-2026 Cell
816-817-5776 Fax

6 attachments



image001.png
9K

Boise Cascade

 **image002.png**
1K

 **image003.jpg**
1K

 **image004.png**
1K

 **image005.png**
1K

 **Calc w holes.pdf**
236K