## **Final Inspection Report Inspection Summary**

Permit #: PRCOM20191955, Building Permit - Commercial Permit Project Title: ATTIC STORAGE OF LEES SUMMIT Address: 920 NE DEERBROOK ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Occupancy Inspection - Planning	Jennifer Thompson, Planner	Failed	Friday, January 29, 2021	
Corrective Action Required 1	The landscaping was not complete at the time of inspection. Will need to coordinate with the building inspector to consider time frame for completion.			
Corrective Action Required 2	Areas noted for insufficiency were the trash enclosure area, the median separating the two properties, area around the building, etc.  The trash enclosure gate was not complete at time of inspection. A solid gate is			
Corrective Action Required 3	·	proving this buildin		
Corrective Action Required 4 Corrective Action Required 5	It was noted the wind interior of the building of the site will require ge time of inspection as was	ows facing M-291 seeme ould be seen. neral site clean up. Larg s a trash roll-off containe	ble space and signage was	
Corrective Action Required 6	Planning will be able to	issue a temporary occupa	are complete. Once complete, ncy for the remaining items.	

	south elevation.	Will they remain like that?	They seemed unfinished.
Comments:			