

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20210222, Public Works Right of Way Permit Address: 1125 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Partial Monday, February 08, 2021

Corrective Action Required

1 Miscellaneous Correction No crews onsite as of 9am. A traffic control company has been

hired to set up a proper work zone. I I'll check back in a couple

of hours to see if crews have arrived.

Corrective Action Required

2 Miscellaneous Correction Crews are onsite removing concrete in the median. Streetwise

has set up a MUTCD compliant traffic zone. We will continue to

monitor.

Corrective Action Required

3 Misc Site visit: No workers were onsite 2/2/21. The area around the

pole is fenced off.

Corrective Action Required

4 Miscellaneous Correction Crews only worked this morning. The pole base hole has been

drilled to six feet in depth where bedrock was hit. An engineer

is being cumulated on how to proceed.

Corrective Action Required

5 Miscellaneous Correction Crews were locating/vac excavating utilities on the west side

ROW of Douglas. Traffic control was adequate.

Corrective Action Required

6 Miscellaneous Correction No crews working today. The orange fencing has blown over

into the northbound lane. I called Aaron and he is sending

someone out to fortify the temporary fence.

Corrective Action Required

7 Miscellaneous Correction Crews are boring conduit on west side ROW. Traffic control is

adequate.

Corrective Action Required

8 Miscellaneous Correction No crews working due to bad weather.

Comments: