

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20203528  
Address: 2346 SW HICKORY LN, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	John Morris	Not Ready	Friday, February 19, 2021

Corrective Action Required:

1	Miscellaneous Correction	-Install Basement egress window -Second story exterior braced wall has been compromised. Bracing method requires the wall to be continuously sheathed with a wood structural panel on all sheathable surfaces with 6" oc edge and 12" field fastening. Bedroom 3 where covered patio roof meets second story exterior wall. Provide engineered solution for repair, field repairs are not adequate -Anchor steel columns in basement
---	--------------------------	--

**Comments:**