

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20204993
Address: 180 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Michael Harkins	Failed	Friday, March 19, 2021

Corrective Action Required:

1	Misc	- FIRE CAULK ELECTRICAL PENETRATIONS IN NORTH FIRE WALL - - FIRE CAULK TO DECK ABOVE RESTROOMS - - FIRE CAULK / FIRE TAPE DRYWALL REPAIR ABOVE MOP SINK - - COMPLETE VENTS TO ROOF IN RESTROOMS - - CHANGING ROOMS G4 PARTITION IS CONTINUOUS FROM SLAB TO UNDERSIDE OF DECK PER PLAN -
---	------	--

Comments: