CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20204231Address:102 NW GRADY CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	1:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Robb Popp	Failed	Wednesday, April 07, 2021
Corrective	Action Required:			
1	Misc	-THE CORRECTIONS MADE THE TRUSSES NOTCHED IN MENTIONED IN THE REPO FOR TRUSSES IN THE MAS	ddress notched trusses garage/master closet HE CORRECTIONS MADE AT THE GARAGE TRUSSES ARE NOT PER THE REPORT, IE TRUSSES NOTCHED IN THE MASTER CLOSET ARE NOT REPAIRED OR ENTIONED IN THE REPORT. PROVIDE ENGINEERED LETTER AND CORRECTION OR TRUSSES IN THE MASTER CLOSET AND AND DOCUMENTATION THAT THE DRRECTIONS MADE TO THE GARAGE TRUSSES IS ADEQUATE	
			niddle 1/3 of width of plate furr out rec room-Seal gap	

Comments: