

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Michael Harkins	Failed	Thursday, March 25, 2021

Corrective Action Required:

1	Misc	- PROVIDE GFCI PROTECTION @ LAUNDRY OUTLETS (2017 NEC 210.8 (A) (10) - - PROVIDE GFCI PROTECTION @ KITCHEN DISH WASHER OUTLETS PER (2017 NEC 210.8 (D) - - PROVIDE SECONDARY LOCK @ SLIDING GLASS DOORS (LEE'S SUMMIT SECTION 7 1406 (B)) : ABOVE ALL UNITS 444 THRU 459 : - 444 ANTI TIP DEVICE RANGE - - 445 GFCI EACH SIDE OF RANGE AND ISLAND WON'T RESET, DECK RAIL MISSING - - 446 DECK RAIL MISSING, FIRE CAULK LINE SET MECH ROOM CEILING - - 447 - - 448 GUARDS SHALL NOT HAVE OPENINGS THAT ALLOW PASSAGE OF A SPHERE 4" IN DIAMETER (PER 2018 IBC 1015.4) - 449 FIRE CAULK LINE SETS MECH ROOM CEILING - - 450 - - 451 FIRE CAULK CEILING MECH ROOM - - 452 GFCI"s LEFT OF FRIDGE WON'T RESET, FIRE CAULK LINE SET MECH ROOM CEILING - - 453- - 454 -
---	------	--

- 455-
- 456 DECK RAILING 4" SPHERE SHALL NOT PASS -
- 457 -
- 458 GFCI BEDROOM BATH WON'T RESET -
- 459 -

Comments: