CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204750

Address: 2005 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Wednesday, April 14,

Residential 2021

Corrective Action Required:

1 Miscellaneous Tighten anchor bolts garage

Correction Provide 5/8 anchor bolts sq washers PFH portal frame garage S2.0 details 12

Nails studs per code at intersecting wall corners (at braced wall panels) \$1.0

#9

Nail sheathing front wall per code bed #2

CS-WSP S1.0

Tighten anchor bolts basement

Solid block & nail sheathing west basement wall

Provide anchor bolts within 12" of plate break basement

Seal fire blocking ceiling at furr out

Install braced wall panels on interior & exterior per plan rec room each side of

windows

Expose trusses covered patio to verify hangers Provide lateral support per truss details A8

Provide fire resistive rating for exterior wall projection on west side of house, less than 5' from property line, no soffit vents in these areas 2018 IRC R302.1)

Comments: