

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Michael Harkins	Partial	Thursday, April 15, 2021

Corrective Action Required:

1	Misc	: 4TH & 3RD, 2ND FLOOR REQUIRED INSPECTIONS : - STAIRWAYS, CORRIDORS, ELECTRICAL & IT ROOMS :- 461 (ADA UNIT) THE WORK SURFACE SHALL BE 34" INCHES MAXIMUM ABOVE THE FLOOR (1103.12.3.2 PER ICC A117.1-2017) - STROBES, GRAB BARS, THRESHOLD SGD, INSULATE
---	------	--

325A fire caulk
not complete list. MARK HARDING 04/13/2021 2:34 PM

Corrective Action Required:

2	FOURTH FLOOR	Pre final -units approved: 444,445,446,447,448,449,450,451,452,453,454,455,456,457,458 ,459,437,438,439,440,441,442,443,460,462,463,464,465. 431-436; 461,425A,421A,424B, Corridor 412 ADA countertops 34", insulating sink drains, strobes, grab bars, threshold sgd ? Code section ?
---	--------------	---

Corrective Action Required:

3	THIRD FLOOR	3/29/21 339,340,341,342,343,345,346-365,366,367; 345,344. 331-338,
---	-------------	--

324B 332,333,

Corrective Action Required:

4 SECOND FLOOR 4/8/21 4/9/21
239-253; 255 - 263 ;265-267;221A,230,231,232,234,235,236,238,

Corrective Action Required:

5 FIRST FLOOR 4/12/21
119; 122-138;

117 ok
118 ok
119 ok
120 bad GFCI breaker dishwasher,
121 ok
120A fire caulk above panel
122 ok
120A fire caulk ceiling above panel
230 ok
231 ok
232 ok
233 secure #9 breaker service panel
234 ok
235 ok
236 ok
237 service panel secure #9 breaker
238 ok
225A fire caulk
220A fire caulk

Corrective Action Required:

6 THE FOLLOWING Pre Final areas approved are the following;
AREAS ARE see sepertate floor levels.
APPROVED *.

Comments: