

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210181
Address: 105 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	John Morris	Failed	Monday, April 26, 2021

Corrective Action Required:

1	Misc	-PORTAL ONLY- -3" oc fastening at top and bottom plates with double bottom plates -solid blocking fastened 3" oc at panel splices -2x4 below LVL header with two rows of 16D sinker nails 3" oc at braced wall panel top plates per plan, see section view of detail -Install Interior tension straps
---	------	---

Comments: