



April 27, 2021

IQ Homebuilders
Attn: Brett Shelton

Re: 2338 SW Old Port Road (Lot 725, Eagle Creek)

Vista Structural Engineering, LLC, was asked to address the following rough-in inspection item for the house being built at 2338 SW Old Port Road:


Does hole drilled vertically through LVL for wire, as shown on the following page, affect the structural integrity of the LVL? *The hole drilled vertically does not affect the structural integrity of the LVL. The bearing condition is achieved at the studs adjacent to the garage door, and the sheathing along the exterior is uninterrupted along the length of the LVL. We therefore recommend approval of the LVL as it is currently installed, with the drilled vertical hole.*

Our firm appreciates the opportunity to serve you. If you have any questions or if you need anything further, please feel free to contact us.

Sincerely,

Vista Structural Engineering, LLC

Dennis Heier, P.E.



VISTA STRUCTURAL ENGINEERING, LLC

14718 NW DELIA STREET
PORTLAND, OREGON 97229



VISTA STRUCTURAL ENGINEERING, LLC

14718 NW DELIA STREET
PORTLAND, OREGON 97229

- 2 -

PHONE: 971.645.0901
VISTASTRUCTURAL.COM