CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20203857 Address: 2358 SW HICKORY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	John Morris	Failed	Tuesday, May 11, 2021

Corrective Action Required:

-Seal exterior penetrations -Guard rail required where grade below exceeds 30 inches, front stoop	1	Misc	 -Guard rail required where grade below exceeds 30 inches, front stoop -No building address, minimum 4 inch height, half inch stroke, on contrastin background and in illuminated area -Provide joist hangers at Garage landing. Address improper stair rise at landing in garage, complete guard rail installation & open risers may not exceed 4 inches -Install anti-tip device at range
--	---	------	---

Comments: