CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204988

Address: 310 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Tuesday, May 11, 2021

Residential

Corrective Action Required:

1 Miscellaneous Correction

-Frame front covered porch per code (full length ridge beam, rafter ties, collar ties, hangers, rafter to top plate connection, etc.) or use designed trusses on

approved plans

- (2 x 8 ridge per engineer letter) -Fireblock dead spaces in garage
- -Hook up bath fan in bed 5 (in soffit now)
- -Address cut joists above mechanical in dead space in kitchen
- -Fireblock dead space in kitchen
- -Fireblock dead spaces and soffit
- -Provide plate at bottom of header in dining
- -Provide jack studs at ends of LVL header in dining
- -Secure snow blocking bed 4
- -Minimum (4) 2x4 stud pack at each girder truss bearing location
- -Seal dead space in master
- -Support roof sheathing with solid framing at valleys
- -Tie 2x6 wall to exterior bedroom wall
- -Seal penetrations and gaps in top fireblocking at fur out walls
- -Provide vertical fireblocking 10' OC max at fur out walls
- -Fireblock beam webs in finished wall
- -Anchor top of basement wall under beam

SEAL TOP PLATE PENETRATIONS BASEMENT BATH pool

PLANS SHOW UNFINISHED BASEMENT

Comments: