

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Michael Harkins	Partial	Monday, May 17, 2021

Corrective Action Required:

1	Misc	413 -AFCI/GFCI at dishwasher circuit 414 -install another tip at range -Self closing and latching door at corridor 415 -faulty exterior GFCI receptacle 418 -loose guardrail at balcony 1-4A panel room, open panel for label. Correct fire damper control in wall over door.
---	------	---

Inspected and OK

-404 ,407,409,410,420,419,422,428,429, 401, 402, 403, 405, 406, 408, 411,
412, 416, 417, 421, 423, 424, 425, 426, 427

Corrective Action Required:

2	FOURTH FLOOR	Pre final -units approved: 444-459,431- 443 ,460-465. , 425A,421A,424B, Corridor 412 5/13/21
---	--------------	--

Following
"B" side
Inspected 401- 412; 416,417, 419-429;

Corrective Action Required:

3 THIRD FLOOR 3/29/21
331-367;
324B

5/17/21
301,303,304,305,306,307, APPROVED
322, 323,324,326,327,328,329, APPROVED

302 REPAIR/REPLACE GFCI BATH NEAR LAUNDRY
325 PROVIDE ANTI TIP DEVICE RANGE
PROVIDE ROOM # SIGNS IN CORRIDOR

Corrective Action Required:

4 SECOND FLOOR 4/8/21 4/9/21
; 255 -263 ;265-267;221A,230-253;
225A ok
220A ok

Corrective Action Required:

5 FIRST FLOOR 4/12/21
117--138;

120A ok

Corrective Action Required:

6 THE FOLLOWING AREAS ARE APPROVED
Pre Final areas approved are the following;
see sepertate floor levels.
*:

Comments: