## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614 Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial		Robb Popp	Partial	Thursday, May 20, 2021	
Informational: 1 THIRD FLOOR		—AREAS APPROVED—			
- '					
		***BUIDING C***			
		PRE ROCK:			
		3019-3031 MECHANICAL ROOM WALLS AND BEHIND SHOWERS			
		ROOMS:3019-3031			
		-STAIRWELL WALLS AND CEILING			
		CORRIDOR TO SHAFT WALL			
		SOFFIT FRAMING IN CORRI	DOR		
		***BUILDING B***			
		PRE ROCK:			
		3003-3016 MECHANICAL RO	DOM WALLS, BEHIND SHOW	'ERS	
		CORRIDOR TO SHAFT WALL	-		
		ROOMS: 3003-3016			
		STAIRWELL WALLS AND CE	ILING		
		***BUILDING A****			

	onal: SECOND FLOOR	ROOMS: 3001, 3002, 3017, 3018, 3037, 3038, 3039, 3041, 3042, 3043, 3044, 3045, 3047 CORIDOOR TO SHAFT WALL OK TO INSULATE EXTERIOR WALLS
Informatic 2		—AREAS APPROVED—
		***BUILDING C***
		ROOMS: 2019-2031 CORRIDOR WALLS AND CEILING TO SHAFT WALL
	onal: FIRST FLOOR	***BUILDING B***
Informatic 3		ROOMS: 2003-2017 CORRIDOR WALLS AND CEILINGS TO SHAFT WALL
		***BUILDING A*** CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 2001,2002, 2017,2018,2040-2045
		—AREAS APPROVED—
		***BUILDING C*** CORRIDOR CEILINGS TO SHAFT WALL ROOMS:1015, 1017, 1021, 1027
		***BUILDING B*** CORRIDOR CEILNGS TO SHAFT WALL
	e Action Required: Miscellaneous Correction	***BUIDING A*** CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE
Corrective 4		**MCAL BUILDING** PRE ROCK: MECHANICAL ROOM 165 NORTH WALL ROOM 1057 OK TO ROCK FOR ELECTRICAL GEAR EAST AND SOUTH WALLS
		-EXPOSE AND SEAL PENETRATIONS AT SHAFT WALL PER UL LISTING
		*5-20
		3040- COMPLETE SPRIKLER INSTALLATION
		2035A- FLASH OPENINGS
		2047-NOT INSPECTED
		1023-REPAIR SHEAR WALL SHEATHING, ADD STUDS AT OVER NOTCHED STUDS IN SHEAR WALL
		1025-REPAIR SHEAR WALL SHEATHING BOTH WALLS

**Comments:**