## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20211173 Address: 302 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Erosion Control		Michael Harkins	Failed	Thursday, May 20, 2021	
Corrective Action Required:					
1	DCM2 ESC	DEFICIENT EROSION CON	ENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS ADEQUATE EROSION CONTROL PROVIDED.		
	DEFICIENT	UNTIL ADEQUATE EROSIO			
	INSTALLATION				
Corrective Action Required:					
2	DCM6 ESC INSP				
	DENIED STREET				
	CLEAN UP	INSPECTION(S) BEING PER	FORMED.		
		- MAINTAIN SILT FENCE -			
		- MAINTAIN GRAVEL FILTE	R -		

- CLEAN STREET -

## **Comments:**