## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20211044 Address: 218 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	n:	Inspector:	Outcome:	Date:	
Erosion C	Control	Michael Harkins	Failed	Thursday, May 20, 2021	
Corrective Action Required:					
1	DCM2 ESC	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPEC			
	DEFICIENT	UNTIL ADEQUATE EROSIO	EQUATE EROSION CONTROL PROVIDED.		
	INSTALLATION				
Corrective Action Required:					
2	DCM6 ESC INSP	REQUESTED INSPECTION(S) DENIED. STREET CLEAN UP REQUIRED			
	DENIED STREET	IMMEDIATELY, AND SHAL	L BE COMPLETED PRIOR TO	REQUESTED	
	CLEAN UP	INSPECTION(S) BEING PER	FORMED.		

- MAINTAIN SILT FENCE -

- MAINTAIN GRAVEL FILTER -
- CLEAN STREET -

## **Comments:**