CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204954

Address: 345 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Friday, June 11, 2021

Residential

Corrective Action Required:

1 Misc Install back ordered windows

Tyvek tape nail penetrations garage Fire block furr outs sales office Tighten anchor bolts sales office

Support soffit in sales office to joist above Secure SCH 40 column foyer at stairway Seal fire blocking chases in great room Support VERTICAL 2" &'smaller DWV

Vent bath exhaust to daylight Nail corners at braced wall panels

Nails triple LVL joist hanger main floor bath Seal HVAC CHASE behind refrigerator Provide 3" SCH 40 column garage per plan

Provide joist hanger basement between LVLs & stairway

Provide anchor bolts SCH 40 column near furnace

Seal vertical to horizontal fire blocking north wall gym & closet

Provide vertical fire block & seal at foundation wall every 10' gym closet

Fire block (insulate) beam pockets

Seal upward penetration sump discharge near service panel & bore left of

service panel

Fire block (insulate) soffit above service panel

Provide 4 stud pack at GT bearing points per roof plan Fire block insulate tub trap jack n Jill bath Seal dead space master bed door Seal dead space master water closet Seal top plate master shower seat Seal dead space master closet Seal top plate bath #2 DWV Seal dead space at door to bed # 2

Comments: