CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204957

Address: 2041 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Thursday, June 17,

Residential

Corrective Action Required:

1 Misc Builder requested garage portal wall framing and rear patio roof framing only:

-Nail the garage PFH wall sheathing to sill plate with 8d @ 3" oc

-Install straps

-Tie down trusses to rear porch header

**Please do not cut out too much of the bottom garage PFH wall plates

2021

Corrective Action Required:

2 Miscellaneous THIS HOUSE IS NOT READY FOR ROUGH IN

CORRECT BELOW ITEMS BEFORE CALLING FOR INSPECTION

THIS LIST IS INCOMPLETE AND SUBJECT TO CHANGE

Solid block sheathing breaks and nail per plan/ per code (no staples) sheets

S1.0

Exterior bracing WSP shall be not less than 48" total at end of braced wall line Nail stud to stud and abutting studs at intersecting wall corners (at braced wall

panels)

Provide 4 studs at GT bearing points per roof plan

Provide LIBs per plan

Comments: