

Inspection Summary

Permit #: PRSUBD20181667, Development - Subdivision
Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous PWORKS Inspection	Steve Robbins	Failed	Friday, June 18, 2021

Corrective Action Required

1	Miscellaneous Correction	I have sent Doug Park, the developer an email asking that we receive the remaining maintenance bonds for the curb and the pavement. I also asked that the erosion control be cleaned up in the subdivision. I let him know we would be stopping permits and building inspections if we did not get the punch list taken care of.
---	--------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Corrective Action Required

2	Misc	I called Doug Park this morning and left a VM for him to call me back about the punch list items and erosion control issues for Whispering Woods 1st Plat.
---	------	------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: