



July 8, 2021

Summit Homes  
120 SE 30<sup>th</sup> St.  
Lee's Summit, MO 64082

**RE: Field Issue of hole in floor joist for Lot #82 Woodside Ridge – 334 NW Ambershame Dr. Lee's Summit, MO 64081 – Permit # PRRES20204861**

This letter addresses the field issue of 2-1/4" hole in floor joist for Lot # 82 Woodside ridge.

**Hole in floor joists above great room:**

- Hole is approximately 2-1/4" diameter and located 1.75" from edge of floor joist.
- Floor joist is located underneath bath#1's shower drain.
- Floor joists span approximately 13'-8" and is Douglas Fir Larch #2 @ 16" oc.
- Install a 24" length of CS-16 coil strap centered over hole. Install with fasteners per manufacturer's specs.

Sincerely,

A handwritten signature in blue ink, appearing to read "B. Huxol", is written over a light blue horizontal line.

Bradley Huxol, PE

