CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Pool Steel/Bonding - Robb Popp Failed Tuesday, July 13, 2021

Commercial

Informational:

1 Miscellaneous Water bonding to be in line at pump

Correction

Corrective Action Required:

2 Miscellaneous -Complete (4) points to perimeter surface bonding per code and ensure all

Correction steel reinforcement is connected and in contact with perimeter surface

bonding

Comments: