CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20202008Address:2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Sanitary Sewer Construction Inspection		Ronald Paynter	Partial	Tuesday, July 27, 2021	
Informational:					
1	Misc	Got the correct barrel sec and encased drop section	tion form American and set RP 7-7-21	t manhole 1-1. Also set	
Informational:					
2	Misc	They laid 260 feet of sanit	tary pipe today. RP 7-8-21		
Informational:					
3	Misc	manholes 1-2 and 1-3. Th started on line 4. They ex	w out to work on the sanita ey also laid 150 feet of sani posed existing manhole 28 breaker blew a hydraulic h	tary pipe. John's crew 3-230 and were digging	
Informa	tional:		-		
4	Misc	-	er repaired and cored into sanitary pipe. Steve's crew RP 7-12-21	-	
Informational:					
5	Misc	-	blems with their breaker. ⁻ e 1-5. They also laid 50 feet RP 7-13-21		
Informational:					
6	Misc		4-1 and laid 3 sanitary pipe 6, 167, 168 and 169. KC Tes nitary line 1. RP 7-14-21		

Informational:				
7	Misc	John's crew set manhole 4-1 and laid 3 sanitary pipes. Steve's crew laid service laterals for lots 166, 167, 168 and 169. KC Testing was on site doing compaction testing on sanitary line 1. RP 7-14-21		
Informatio	onal:			
8	Misc	John's crew laid 125 feet of sanitary pipe. Steve's crew also laid 125 feet of sanitary pipe. The also set manhole 1-6. RP 7-16-21		
Informatio	onal:			
9	Misc	The inverts have been poured on MH 1-5 and 1-6.I The back hoe broke down this afternoon. The other crew was working toward install MH 4-2, they were backfilling in the road with AB-3. This crew also hit rock so they were moving slow this afternoon.		
Informatio	onal:			
10	Misc	John's crew set MH 4-2 and service lateral for lot 192. They pre-tested the main line underneath Killarney and found they have a leak. They are digging it back up to find the problem. Steve's crew started working on line 2 out of MH 1-2. They laid 100 feet of sanitary pipe. KC Testing was on site doing compaction testing on line 1. RP 7-20-21		
Informational:				
11	Misc	John's crew replaced the broken pipe with a new section connected with strong back fernco's. They laid 150 feet of sanitary pipe and set MH 4-3. Steve's crew laid 100 feet of sanitary pipe and set MH 2-1 They also set service laterals for lots 160 and 161. RP 7-21-21		
Informational:				
12	Misc	John's crew set service laterals for lots 191, 193 and 194. They had KC Testing on site doing compaction testing. Steve's crew laid 100 feet of sanitary pipe. They also set MH 2-2 and service laterals for lots 159, 158 and 157. RP 7-22-21		
Informational:				
13	Misc	John's crew filled the trench on Killarney with KCMMB 4K mixture. They had KC Testing on site doing compaction testing on Line 4. Steve's crew laid 100 feet of sanitary pipe and service laterals for lots 156 and 162. Both crews worked on back filling the lines that were still open for the weekend. RP 7-23-21		
Informational:				
14	Misc	John's crew laid 225 feet of sanitary pipe on line 4. Steve's crew laid 100 feet of sanitary pipe. They also set MH 2-3 and service laterals for lots 155 and 163. KC Testing was on site for compaction testing with both crews. RP 7-26-21		
Informational:				
15	Misc	John's crew poured trench checks and inverts on line 4. Steve's crew back filled laterals and core cut existing MH 9-4. RP 7-27-21		

Comments: