CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211980

Address: 512 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Failed Thursday, July 29, 2021

Residential

Corrective Action Required:

1 Miscellaneous 7-23-21

Correction Portal frame inspection:

-Post address before any further inspections

-Solid block sheathing breaks and nail 3" OC per detail

-Nail top plate to header with (2) rows 16d sinkers 3" OC per detail

-Do not cover

Corrective Action Required:

2 Miscellaneous 7-23-21

Correction Portal frame inspection:

-Solid block horizontal sheathing breaks at garage wall panel and nail 3" OC

per detail

-Nail top plate to header with (2) rows 16d sinkers 3" OC per detail

-Do not cover

Comments: