

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211980
Address: 512 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Thursday, July 29, 2021

Corrective Action Required:

1	Miscellaneous Correction	7-23-21 Portal frame inspection: -Post address before any further inspections -Solid block sheathing breaks and nail 3" OC per detail -Nail top plate to header with (2) rows 16d sinkers 3" OC per detail -Do not cover 7-29-21 -Solid block horizontal sheathing breaks at PFH panels and nail 3" OC per detail -Nail top plate to header with (2) rows 16d sinkers 3" OC per detail -Do not cover
---	--------------------------	---

Corrective Action Required:

2	Miscellaneous Correction
---	--------------------------

Comments: