CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210673

Address: 1619 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Tuesday, August 03,

Residential 2021

Corrective Action Required:

1 Misc -Unable to inspect 3" oc grid nail pattern at garage PFH due to cover

- -security blocking at garage man door and basement walkout
- -header to Jack stud tension straps at garage PFH R602.10.6.2
- -anchor bolt 5/8" diam w/ 2" x 2" x 3/16" plate washer at garage PFH

K602.10.6.2

- -Add joist hangers at tail joist to attic access connection and (3) sgl joists to
- header between garage bays, over 4' -add collar ties garage great room
- -Fireblock fireplace at great room open to attic space at master bed wall
- -Unable to inspect framing at covered deck, remove some panels to allow inspection
- -Seal NM top plate penetration at front entry closet
- -Electrical box at great room floor must be rated for floor use
- -Fireblock vertical to horizontal at all soffit ends of furred downs at finished basement
- -connect 2x4 laid flat at furred downs 3' or more to floor joists above to support ceiling load at finished basement
- -Fireblock between top plate and either foundation wall or framing top plate at finished basement
- -Support pex above finished basement bath closet
- -seal all top plate penetrations at both finished basement bedrooms

-3.5" SCH 40 steel column at W8x15 beam bearing end at basement rec room
walkout corner per plans

Comments: