CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204442

Address: 2009 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Michael Harkins Failed Thursday, August 05,

2021

Corrective Action Required:

1 Misc -Erosion control requires continuous maintenance. Repair damaged sections at

curb and establish methods rear of lot within 48 hours

-provide and maintain gravel filter

-no further inspections until issues are resolved

Corrective Action Required:

2 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS

DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.

- MAINTAIN SILT FENCE UNTIL SOD COMPLETE _

Comments: