



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	LEES SUMMIT POLICE DEPARTMENT - INTERIOR ALTERATIONS AND ADDING FLOOR SPACE TO UPPER LEVEL		
ADDRESS	10 NE TUDOR RD, LEES SUMMIT, MO 64086		
OWNER/OPERATOR NAME	TURNER CONSTRUCTION COMPANY:	TELEPHONE	(816) 283-0555
ADDRESS	1220 WASHINGTON STE 1000 KANSAS CITY, MO 64105 Primary: (816) 283-0555 Cell: (816) 398-5703		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: I-3	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Michael Weissenbach	Failed	Wednesday, August 11, 2021
Occupancy Inspection - Fire	Michael Weissenbach	Failed	Wednesday, August 11, 2021
Corrective Action Required:			
1	1. Cover East side of South waiting room exit sign. 2. Sprinkler System out of date, need annual inspection.		

3. Synchronize strobes for the alarm system.
4. Add chevron to exit sign in basement. x2
5. Remove exit sign by small break room.
6. Strobe in dispatch did not work.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
August 11, 2021	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	