



# LEE'S SUMMIT MISSOURI



## FIRE DEPARTMENT

### NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

<b>BUSINESS NAME</b>	LEES SUMMIT POLICE DEPARTMENT - INTERIOR ALTERATIONS AND ADDING FLOOR SPACE TO UPPER LEVEL		
<b>ADDRESS</b>	10 NE TUDOR RD, LEES SUMMIT, MO 64086		
<b>OWNER/OPERATOR NAME</b>	TURNER CONSTRUCTION COMPANY:	<b>TELEPHONE</b>	(816) 283-0555
<b>ADDRESS</b>	1220 WASHINGTON STE 1000 KANSAS CITY, MO 64105 Primary: (816) 283-0555 Cell: (816) 398-5703		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

### LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: I-3	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

### LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
<b>Alarm Test</b>	Michael Weissenbach	Failed	Wednesday, August 11, 2021
Corrective Action Required:			
1. Synchronize strobes for the alarm system.			
2. Strobe in dispatch did not work.			
3. Alarm was not received by the fire department dispatch.			
4. FACP labeled with panel # and breaker #.			
5. Breaker labeled FACP.			

**Occupancy Inspection - Fire**

Michael Weissenbach

Failed

Wednesday, August 11, 2021

## Corrective Action Required:

- 1
  1. Cover East side of South waiting room exit sign.
  2. Sprinkler System out of date, need annual inspection.
  3. Synchronize strobes for the alarm system.
  4. Add chevron to exit sign in basement. x2
  5. Remove exit sign by small break room.
  6. Strobe in dispatch did not work.

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
August 11, 2021	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	