CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211352

Address: 4824 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Steve Robbins Failed Friday, August 13, 2021

Corrective Action Required:

1 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. SHALL PROVIDE GRAVEL FILTER DEFICIENT AT LOT ENTRANCE, RESTORE EROSION CONTROL ALONG THE STREET, AND

AT LOT ENTRANCE, RESTORE EROSION CONTROL ALONG THE STREET, AND

INSTALLATION CLEAN UP THE STREET ON BOTH SIDES

NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.

Corrective Action Required:

2 Misc Field inlet in back of property is clogged up due to excessive silt build up. The

water cannot drain into the inlet and is causing the home at 4828 Jamestown to have water backing up into their yard. Please take care of this right away. No

inspections until this is taken care of.

Comments: