## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRSUBD20202008Address:2030 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:		
Sanitary Sewer Construction Inspection		Ronald Paynter	Partial	Friday, August 20, 2021		
Informational:						
1	Misc	Got the correct barrel sec and encased drop section	tion form American and set RP 7-7-21	t manhole 1-1. Also set		
Informational:						
2	Misc	They laid 260 feet of sanitary pipe today. RP 7-8-21				
Informational:						
3	Misc	manholes 1-2 and 1-3. Th started on line 4. They ex	w out to work on the sanita ey also laid 150 feet of sani posed existing manhole 28 breaker blew a hydraulic h	tary pipe. John's crew 3-230 and were digging		
Informational:						
4	Misc	-	er repaired and cored into sanitary pipe. Steve's crew RP 7-12-21	-		
Informational:						
5	Misc	-	blems with their breaker. <sup>-</sup> 2 1-5. They also laid 50 feet RP 7-13-21	-		
Informational:						
6	Misc		4-1 and laid 3 sanitary pipe: 6, 167, 168 and 169. KC Tes nitary line 1. RP 7-14-21			

Informational:					
	Лisc	John's crew set manhole 4-1 and laid 3 sanitary pipes. Steve's crew laid service laterals for lots 166, 167, 168 and 169. KC Testing was on site doing compaction testing on sanitary line 1. RP 7-14-21			
Information 8 N	iai: ⁄isc	John's crew laid 125 feet of sanitary pipe. Steve's crew also laid 125 feet of			
		sanitary pipe. The also set manhole 1-6. RP 7-16-21			
Informational:					
	Лisc	The inverts have been poured on MH 1-5 and 1-6.I The back hoe broke down this afternoon. The other crew was working toward install MH 4-2, they were backfilling in the road with AB-3. This crew also hit rock so they were moving slow this afternoon.			
Information					
10 N	Лisc	John's crew set MH 4-2 and service lateral for lot 192. They pre-tested the main line underneath Killarney and found they have a leak. They are digging it back up to find the problem. Steve's crew started working on line 2 out of MH 1-2. They laid 100 feet of sanitary pipe. KC Testing was on site doing compaction testing on line 1. RP 7-20-21			
Information	nal:				
	Лisc	John's crew replaced the broken pipe with a new section connected with strong back fernco's. They laid 150 feet of sanitary pipe and set MH 4-3. Steve's crew laid 100 feet of sanitary pipe and set MH 2-1 They also set service laterals for lots 160 and 161. RP 7-21-21			
Information 12 N		John's grow set convise laterals for late 101, 102 and 104. They had KC Testing			
	Aisc	John's crew set service laterals for lots 191, 193 and 194. They had KC Testing on site doing compaction testing. Steve's crew laid 100 feet of sanitary pipe. They also set MH 2-2 and service laterals for lots 159, 158 and 157. RP 7-22-21			
Informational:					
13 N	Лisc	John's crew filled the trench on Killarney with KCMMB 4K mixture. They had KC Testing on site doing compaction testing on Line 4. Steve's crew laid 100 feet of sanitary pipe and service laterals for lots 156 and 162. Both crews worked on back filling the lines that were still open for the weekend. RP 7-23-21			
Informational:					
	Лisc	John's crew laid 225 feet of sanitary pipe on line 4. Steve's crew laid 100 feet of sanitary pipe. They also set MH 2-3 and service laterals for lots 155 and 163. KC Testing was on site for compaction testing with both crews. RP 7-26-21			
Information					
15 N	Лisc	John's crew poured trench checks and inverts on line 4. Steve's crew back filled laterals and core cut existing MH 9-4. RP 7-27-21			
Informational:					
	Лisc	Both crews worked together on line 4 today. They laid 100 feet of sanitary pipe and service laterals for lots 198 and 187. They also had KC Testing on site doing compaction testing. RP 7-28-21			
Information					
	Лisc	Back down to just one crew. They laid 50 feet of sanitary pipe and set MH 4-4. KC Testing was on site doing compaction testing. RP 7-29-21			
Informational:					
18 N	Лisc	Steve's crew back filled and KC Testing was on site doing compaction testing.			

		RP 7-30-21
Inform	ational:	
19	Misc	Steve's crew laid 100 feet of sanitary pipe and service laterals for lots 186 and 185. RP 8-2-21
Inform	ational:	
20	Misc	Steve's crew laid the last 50 feet of sanitary pipe and set MH 4-5 and service lateral for lot 184. KC Testing was on site doing compaction testing. RP 8-3-21
Inform	ational:	
21	Misc	Steve's crew bored into existing MH 9-4 and installed the drop section. They also laid 100 feet of sanitary pipe and set MH 3-1. RP 8-4-21
Inform	ational:	
22 Inform	Misc ational:	Steve's crew laid 100 feet of sanitary pipe. RP 8-5-21
23	Misc	Jone's crew laid 100 feet of sanitary pipe and set service laterals for lots 150, 149, 180 and 179. KC Testing was on site doing compaction testing. RP 8-6-21
Inform	ational:	
24	Misc	Crew is installing pipe from MH 3-1-3-2. They have installed wyes on lots 152 and 177. They will be setting MH 3-2 today.
Inform	ational:	
25	Misc	They laid 100 feet of sanitary pipe and service lateral for lot 153. KC Testing was on site doing compaction testing. RP 8-11-21
Inform	ational:	
26 Inform	Misc ational:	They laid 100 feet of sanitary pipe and service lateral for lot 176. RP 8-12-21
27	Misc	They laid 50 feet of sanitary pipe and set MH 3-3. They also laid service laterals for lots 154, 175, 174 and 173. RP 8-16-21
Informational:		
28	Misc	Steve's crew raised the 2 existing manholes and started pre-testing the sanitary lines. The 30 day clock starts today. RP 8-17-21
Inform	ational:	
29	Misc	They continued to pre test the sanitary lines (mandrel, air and vacuum). RP 8-18-21
Inform	ational:	
30	Misc	More pre-testing the sanitary lines. Looking for a leak in sanitary line 3. RP 8-19-21
Inform	ational:	
31	Misc	They found and repaired the leak on line 3. No other problems during the pre-testing. Now we are just waiting for the 30 days to expire for the actual testing. RP 8-20-21

## **Comments:**