## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20210596 Address: 2102 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	ו:	Inspector:	Outcome:	Date:
Erosion Control		Michael Harkins	Failed	Thursday, September 02, 2021
Corrective	Action Required:			
1	DCM2 ESC	DEFICIENT EROSION CONT	ROL INSTALLATION. NO FUF	RTHER INSPECTIONS
	DEFICIENT	UNTIL ADEQUATE EROSION CONTROL PROVIDED.		
	INSTALLATION			
		MAINTAIN SILT FENCE		
		CLEAN GRAVEL FROM STRE	ET	
Corrective	Action Required:			
2	DCM2 ESC	DEFICIENT EROSION CONT	ROL INSTALLATION. NO FUR	RTHER INSPECTIONS
	DEFICIENT	UNTIL ADEQUATE EROSION	N CONTROL PROVIDED.	
	INSTALLATION	- MAINTAIN GUTTER BUDD	Y AT CURB INLET & REMOV	E SEDIMENT BUILD UP -

Comments: